



Оцинкованная сталь, нержавеющая сталь по запросу

Аксессуары

BH	H=GH+BH						L= 45 мм		L= 35 мм	
	GH=18	GH=30	GH=36	GH=40	GH=50	GH=60	со стопором	без стопора	со стопором	без стопора
-16	2	14	20	24	34	44	9100-0402	9100-0402F		
-14	4	16	22	26	36	46	9100-0404	9100-0404F		
-12	6	18	24	28	38	48	9100-0406	9100-0406F	9100-0606	9100-0606F
-10	8	20	26	30	40	50	9100-0408	9100-0408F	9100-0608	9100-0608F
-8	10	22	28	32	42	52	9100-0410	9100-0410F	9100-0610	9100-0610F
-5	13	25	31	35	45	55	9100-0413	9100-0413F	9100-0613	9100-0613F
-4	14	26	32	36	46	56	9100-0414	9100-0414F	9100-0614	9100-0614F
-2	16	28	34	38	48	58	9100-0416	9100-0416F	9100-0616	9100-0616F
0	18	30	36	40	50	60	9100-0418	9100-0418F	9100-0618	9100-0618F
+2	20	32	38	42	52	62	9100-0420	9100-0420F	9100-0620	9100-0620F
+4	22	34	40	44	54	64	9100-0422	9100-0422F	9100-0622	9100-0622F
+6	24	36	42	46	56	66	9100-0424	9100-0424F	9100-0624	9100-0624F
+7	25	37	43	47	57	67	9100-0425	9100-0425F	9100-0625	9100-0625F
+8	26	38	44	48	58	68	9100-0426	9100-0426F	9100-0626	9100-0626F
+10	28	40	46	50	60	70	9100-0428	9100-0428F	9100-0628	9100-0628F
+12	30	42	48	52	62	72	9100-0430	9100-0430F	9100-0630	9100-0630F
+14	32	44	50	54	64	74	9100-0432	9100-0432F		
+16	34	46	52	56	66	76	9100-0434	9100-0434F		
+17	35	47	53	57	67	77	9100-0435	9100-0435F	9100-0635	9100-0635F
+18	36	48	54	58	68	78	9100-0436	9100-0436F		
+20	38	50	56	60	70	80	9100-0438	9100-0438F	9100-0638	9100-0638F
+22	40	52	58	62	72	82	9100-0440	9100-0440F	9100-0640	9100-0640F
+24	42	54	60	64	74	84	9100-0442	9100-0442F	9100-0642	9100-0642F
+26	44	56	62	66	76	86	9100-0444	9100-0444F	9100-0644	9100-0644F
+27	45	57	63	67	77	87	9100-0445	9100-0445F		
+29	47	59	65	69	79	89	9100-0447	9100-0447F		
+32	50	62	68	72	82	92	9100-0450	9100-0450F		
+35	53	65	71	75	85	95	9100-0453	9100-0453F		
+37	55	67	73	77	87	97	9100-0455	9100-0455F		